

**Description** Boiler 2 Hydrated lime system inspection**Equipment** 0700-04-135 HYDRATED LIME INJECTION LANCES #2**Work Type** Routine**Status** 70-Tech Complete**Supervisor****Priority** 3**WO Class** 3 Schedule**Criticality** 2**Assigned To****Requested Comp****Scheduled Date****Completed Date** 11/12/2021**Planner****Estimated Cost** \$0.00**WO Type****Total Planned** \$0.00**Entered By** Kevin Lawrence**Area** 04-Boiler Island**Entered Date** 10/29/2021 09:31:42.939**Department** Emissions Control**Requestor** Kevin Lawrence**Plant Status** 3 Unit 2 Outage**Approver****Account** 8405**Equipment** 0700-04-135 HYDRATED LIME INJECTION LANCES #2**Serial #****Equip. Specs****Equip. Down** ☐**Down Hours** 0**Safety** ☐**Service****Comments** Remove and inspect all for lances. Clean as needed. Inspect and clean discharge piping.**Safety Procedures / Permits**

1 Safe Work Permit

2 Lock Out Tag Out

4 Confined Space Entry

\*RT000383-02\*

Job OK - Production \_\_\_\_\_ Date \_\_\_\_\_

Job OK - Maintenance \_\_\_\_\_ Date \_\_\_\_\_

Repair Remarks \_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

Failure (Y or N) \_\_\_\_\_ Production Lost \_\_\_\_\_

New Serial # \_\_\_\_\_

Critique for Work Order # \_\_\_\_\_

Hours Planned \_\_\_\_\_ Actual Hours Worked \_\_\_\_\_

This job ran OVER / UNDER (circle one) the estimated hours because

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_